

## CENTRAL INTELLIGENCE AGENCY

## INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL - U.S. OFFICIALS ONLY  
SECURITY INFORMATION

50X1-HUM

COUNTRY Hungary

REPORT

SUBJECT Shipbuilding in Budapest

DATE DISTR. 6 August 1953

NO. OF PAGES 1

DATE OF INFO.

REQUIREMENT

50X1-HUM

PLACE ACQUIRED

REFERENCES

50X1-HUM

THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE.  
THE APPRAISAL OF CONTENT IS TENTATIVE.  
(FOR KEY SEE REVERSE)

50X1-HUM

1. In the Ghiurgiu-Dej (Ganz) Shipyard, work continues on the series 1,100-ton ships destined for Soviet use. However, vessel [ ] completes the Soviet requirements in so far as reparations are concerned and all hulls from [ ] are built against payments. 50X1-HUM
2. In view of this understanding, the shipyard has undertaken to provide the USSR with 50 vessels in this series over a 3-year period at a rate of 17 vessels a year. However, because of the steel shortage and other construction difficulties, the USSR has now agreed to accept the reduced number of 14 vessels for 1953. 50X1-HUM
3. In order to produce these 14 vessels the production capacity of the shipyard will be taxed to the full. Partial relief is expected by the use of pre-assembly methods and more welding. In addition to the normal slipways, these vessels are also being built under the gantry crane behind the outfitting berth. It is intended to slide them over the proper slipways for launching. After launching complete outfitting takes only an average of 14 days.
4. It is because of this forced production that the construction of the new 2,000-ton Messart vessel was stopped. An additional reason is that it was found that the plan to use for its construction a large number of old plates destined for a prewar ship which, in the meantime, have been stored near the electrical workshop, was impracticable, because the old plates were measured and out for rivetted constructions whereas the new plans call for a large amount of welding and the plates were therefore unsuitable.

5.

50X1-HUM

SECRET/CONTROL - U.S. OFFICIALS ONLY

STATE	X	ARMY	X	NAVY	X	AIR	X	FBI		AEC									
-------	---	------	---	------	---	-----	---	-----	--	-----	--	--	--	--	--	--	--	--	--

(Note: Washington Distribution Indicated By "X"; Field Distribution By "#")